



April 26, 2019

The Secretary, Listing Department
BSE Limited
Phiroze Jeejeebhoy Towers,
Dalal Street,
Mumbai - 400 001.
Maharashtra, India.
Scrip Code: 500470/890144

The Manager, Listing Department
National Stock Exchange of India Limited
Exchange Plaza, 5th Floor, Plot No. C/1,
G Block, Bandra-Kurla Complex, Bandra (E),
Mumbai - 400 051.
Maharashtra, India.
Symbol: TATASTEEL/TATASTEELPP

Dear Sir, Madam,

Sub: Incident at Tata Steel UK Port Talbot site

This is to inform you that shortly after 3.30 a.m. UK time today, an incident occurred at the Tata Steel UK (TSUK) Port Talbot site involving a spillage of molten iron during the routine transfer from Blast Furnace to the Steel Making Facilities. The spillage led to fire which was extinguished by TSUK emergency services supported by members of the Mid and West Wales Fire and Rescue Service. Two employees suffered minor injuries and both have been released following treatment.

Further investigations are underway to assess the damage and potential material impact on production, if any.

Should there be any further material developments, the same will be disseminated appropriately.

This disclosure is made in compliance with Regulation 30 of the Securities and Exchange Board of India (Listing Obligations and Disclosure Requirements) Regulations, 2015.

This is for your information and records.

Thanking you.

Yours faithfully,
Tata Steel Limited

Parvatheesam K
Company Secretary &
Chief Legal Officer (Corporate & Compliance)

TATA STEEL LIMITED

Registered Office Bombay House 24 Homi Mody Street Fort Mumbai 400 001 India
Tel 91 22 6665 8282 Fax 91 22 6665 7724 website www.tatasteel.com
Corporate Identity Number L27100MH1907PLC000260